ERICO® CADWELD®

BF connection (No spacer)



VIEW A–A

Prior to making a connection, read and follow instructions on IPP and special instructions below.

1. Insert two bars in each side of the mold.
   Position bar as shown with 1/4" [6mm] gap centered at the tap hole.

2. Bars must be flat to keep mold closed.

3. Lock mold halves together using ERICO EZ clamp,
   Make sure there are no gaps in mold.

WARNING:
1. ERICO products shall be installed and used only as indicated in ERICO product instruction sheets and training materials. Instruction sheets are available at www.erico.com and from your ERICO customer service representative.
2. ERICO products must never be used for a purpose other than the purpose for which they were designed or in a manner that exceeds specified load ratings.
3. All instructions must be completely followed to ensure proper and safe installation and performance.
4. Improper installation, misuse, misapplication or other failure to completely follow ERICO's instructions and warnings may cause product malfunction, property damage, serious bodily injury and death.

SAFETY INSTRUCTIONS:
All governing codes and regulations and those required by the job site must be observed.
Always use appropriate safety equipment such as eye protection, hard hat, and gloves as appropriate to the application.

CADDY, CADWELD, CRITEC, ERICO, ERIFLEX, ERITECH, and LENTON are registered trademarks of ERICO International Corporation.

©2014 ERICO International Corporation